


Polywater® SqueakyKleen™

CABLE CLEANER

- Removes pik without alcohol
- Minimal wiping (2 wipes only)
- No residue
- Safe to use on ribbon fiber
- Fans fiber quickly
- Fibers so clean they *squeak!*



polywater.com/squeekykleen.asp

Polywater® SqueekyKleen™ Cable Cleaner

New **SqueekyKleen™** cleans and fans fiber in two wipes without alcohol, saving time and money. Hear the difference! No follow-up with alcohol required to get fibers squeaky clean and separated for fast and easy splicing. **SqueekyKleen™** reduces chemical odors and harmful vapor concentrations in splice trailers and vaults while being less harsh on hands.

SqueekyKleen's unique formulation and specially designed high-performance towelette work to remove pik from the entire surface of loose tube or ribbon fibers, leaving no residue.

SqueekyKleen™ helps keep splice equipment clean for better fiber alignment and splice quality. Will not harm acrylate on loose tube cable or Mylar® on ribbon fiber.

SPECIFICATIONS

Cleaning: When wiping a 3-foot section of 12-count fiber from a buffer tube, the pre-saturated towel will squeak and fan fibers with 2 wipes.

Solvency Power: At 68° F (20° C), will dissolve .020" (.5mm) film of PE/PJ or ETPR grease completely from cable jacket with less than two minutes of vigorous agitation (no wiping).

Residue: When placed on a clean glass panel and dried, the solvent shall leave less than 100 parts per million of residue (<100 ppm).

Water Content: When tested by the ASTM 1533B method, water content shall be less than 75 ppm.

Flash Point: When tested via a Pensky-Martin Closed Cup Test (ASTM D93), the cleaner shall have a flash point above 140° F (60° C).



CATALOG NUMBER	DESCRIPTION	STANDARD SHIPPING PACKAGE
TC-1	SqueekyKleen™ Telcom Cleaner—Saturated 8" x 12" (20 cm X 30 cm) Wipe	144
TC-16LF	16-Oz (0.47 Liter) SqueekyKleen™ Telcom Cleaner w/Flip Top cap	12
TC-16LR	16-Oz (0.47 Liter) SqueekyKleen™ Telcom Cleaner w/Sprayer	12
TC-35LF	Qt (0.95 Liter) SqueekyKleen™ Telcom Cleaner w/Flip Top cap	12
TC-35LR	Qt (0.95 Liter) SqueekyKleen™ Telcom Cleaner w/Sprayer	12
TC-128	1-Gal (3.8 Liter) SqueekyKleen™ Telcom Cleaner	4
TC-384	3-Gal (11.4 Liter) SqueekyKleen™ Telcom Cleaner (5-gal pail)	1
TC-640	5-Gal (19 Liter) SqueekyKleen™ Telcom Cleaner	1
TC-96	3-Qt (2.84 Liter) SqueekyKleen™ Telcom Cleaner (1-gal pail)	4
TC-D300	SqueekyKleen™ Saturated 6" x 5" (15 cm X 13 cm) Wipe Canister	6
TC-DRUM	Drum SqueekyKleen™ Telcom Cleaner	1
TC-1D42	42 TC-1 in a Dispenser Pack	1

Important Notice: The statements here are made in good faith based on tests and observations we believe to be reliable. However, the completeness and accuracy of the information is not guaranteed. Before using, the end-user should conduct whatever evaluations are necessary to determine that the product is suitable for the intended use.

American Polywater expressly disclaims any implied warranties and conditions of merchantability and fitness for a particular purpose. American Polywater's only obligation shall be to replace such quantity of the product proven to be defective. Except for the replacement remedy, American Polywater shall not be liable for any loss, injury, or direct, indirect, or consequential damages resulting from product's use, regardless of the legal theory asserted.

American
Polywater®
 Corporation

1-800-328-9384
 1-651-430-2270
 fax 1-651-430-3634
 support@polywater.com (e-mail)